

# STATUSWATCH

LINE SIGN

StatusWatch






See more of your facility at a glance with the StatusWatch Line Sign application. View any number of screens in rotation and know instantly where help is needed.

- Display the status of many machines or andon devices in real time.
- Rotate through multiple screens of information on a timer.
- Fully configurable using a simple settings interface.
- Live version sync allows for hassle-free software upgrades.
- Calculate performance metrics using data from multiple stations.
- Pull data from any OPC server, or from StatusWatch itself.
- Display web pages and other important documents as desired.
- Customizable layout allows for topographical view of your facility.
- Supports LCD and LED displays.
- One-click client installation makes deployment easy.
- System Requirements:
  - Operating System – Windows XP or Higher
  - Computer and Processor – 1Ghz or Faster
  - Memory – 512 mb
  - Disk Space – 500 MB
  - Software – Dotnet 3.5 Service Pack 1

Shop Floor Display



Timer Display

Black Iron					
08/28/2013 09:30					
Goal	Plan	Act	Dwn	Timer	
20	3	0		-20:53	
SS33C	SS35C	SS36C	SS37C	SS39C	SS40C
R	R	R	R	R	R
40:53	40:53	40:53	40:53	40:53	40:53

Pacer Bar

Thursday, June 06, 2013 09:18:24 AM					
Current Job			Machine State		
Progress			Status AUTOMATIC		
Part Number	Plan	Actual	Down Time	Up Time	
1001	61%	45%	26%	74%	
Availability	74%				
OEE	72%				
Efficiency	74%				